Westhertzanon Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2330Work Order Type: WeatherizationAudit Name: 14014SO2330

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO2330 WINCHESTER, TN 37398

Alt. Client ID: FRANKLIN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Client Name:
Client ID: 14014SO2330
Alt. Client ID: FRANKLIN

Work Order (Bid Form)

Work Order Name: 14014SO2330 Report Run On: 5/28/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 7

	Itration Redctn			Componen	เร			Inspecte	
ELECT 2. W/S 3. INST	L AROUND CEILING AN RICAL FRONT DOOR TALL NEW BACK DOOR OF AND CEILING REPAIR	UNIT AND) REF	RAME INSID					
		Estimated Ad					Actual		
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Miscellaneous Supplies	Infiltration Reduction	Each	1						
Labor	LABOR	Hour							
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Comment CAULK	ndow Sealing CALL WINDOWS AND IN AND 1 WINDOW PANE	ISTALL W	INDOV		REPLAC	E 1 S/V	V	Inspecte	
Comment CAULK PANE	ALL WINDOWS AND IN AND 1 WINDOW PANE			V LOCKS /	REPLAC		N Actual		
Comment CAULK PANE A Material / Labor	ALL WINDOWS AND IN	Units Each Window	INDOV Qty 14	V LOCKS /	REPLAC	E 1 S/V	V	Inspecte	
Comment CAULK PANE A Material / Labor Windows	ALL WINDOWS AND IN AND 1 WINDOW PANE Description / Comment	<i>Units</i> Each	Qty	V LOCKS /	REPLAC		N Actual		
Comment CAULK PANE A Material / Labor Windows Labor	CALL WINDOWS AND IN AND 1 WINDOW PANE Description / Comment Window Sealing	<i>Units</i> Each Window Each	Qty 14	V LOCKS /	REPLAC		N Actual		
Comment CAULK PANE A Material / Labor Windows Labor	CALL WINDOWS AND IN AND 1 WINDOW PANE Description / Comment Window Sealing	<i>Units</i> Each Window Each	Qty 14	V LOCKS /	REPLAC		N Actual		
Comment CAULK PANE A Material / Labor Windows Labor	CALL WINDOWS AND IN AND 1 WINDOW PANE Description / Comment Window Sealing	<i>Units</i> Each Window Each	Qty 14	V LOCKS /	REPLAC		N Actual		
Comment CAULK PANE A Material / Labor Windows Labor	CALL WINDOWS AND IN AND 1 WINDOW PANE Description / Comment Window Sealing	Units Each Window Each Window	Qty 14 14	V LOCKS /	REPLAC	Qty	N Actual	Total	
	CALL WINDOWS AND IN AND 1 WINDOW PANE Description / Comment Window Sealing	Units Each Window Each Window	Qty 14 14	Estimated Unit Cost	REPLAC	Qty	Actual Unit Cost		

Client Name:
Client ID: 14014SO2330
Alt. Client ID: FRANKLIN

Work Order (Bid Form)
Work Order Name: 14014SO2330

DOE Weatherization Assistant Version 8.5.0

Commont DI OW	C Ins. R-30			Componen	ts	Inspected			
Comment BLOW	OVERHEAD IN UPSTAIR	(S AREA		Estimated	1		Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1008						
2 Labor	Attic Insulation - Blown Cellulose - R-30	SqFt	1008						
Other Detail						1	1		
]] []			
			Magazir	e Sub Total:] []	Sub Total:		
			iweasur (e Sub Total.			oub rotui.		
Measure 4 DW Comment									
Comment	H Pipe Insulation			Componen Estimated				Inspecte	
# Material / Labor	H Pipe Insulation Description / Comment	Units	Qty	Componen Estimated Unit Cost		Qty	Actual Unit Cost	Inspected Total	
	•	<i>Units</i> Each		Estimated	1	Qty	Actual		
# Material / Labor	Description / Comment		Qty	Estimated	1	Qty	Actual		
# <i>Material / Labor</i> 1 Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	1	Qty	Actual		
# Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	1	Qty	Actual		
# Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated	1		Actual		
# Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost		

Measure 5 Flo Comment	or Ins. R-19			Componen	Inspecte			
				Estimated	•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1008					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1008					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 6 Wa Comment	II Insulation			Componen Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1214					
2 Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1214					
Other Detail						1		
			Measure	e Sub Total:		,	Sub Total:	
Field Notes:								

	ure 7 Replace Htg. System Components							Inspecte	
IN UPS	L (2) 220 ELECTRIC WA FAIRS BEDROOM - RUN RS AND NEW BREAKEF	I NEW W					1		
			Estimated Act				Actual	ıl	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Heating Equipment	Space Heater - 24 kBtu/h Elec Existing, 27 - 38 kBtu/h Elec Post	Each	2						
Labor	Space Heater - 24 kBtu/h Elec Existing, 27 - 38 kBtu/h Elec Post	Each	1						
Other Detail									
			Measur	e Sub Total:] :	Sub Total:		
Measure 8 Fix I	mproper Venting (Cloth	es Dryer)						
# Material / Labor			,	Componen Estimated			Actual	Inspecte	
	Description / Comment	Units	Qty	•		Qty		Inspecte	
	•	<i>Units</i> Each		Estimated	<u> </u>	Qty	Actual		
Health and Safety Items	•		Qty	Estimated	<u> </u>	Qty	Actual		
Health and Safety Items Labor	Metal Flex	Each	Qty 1	Estimated	<u> </u>	Qty	Actual		
Health and Safety Items Labor	Metal Flex	Each	Qty 1	Estimated	<u> </u>	Qty	Actual		
1 Health and Safety	Metal Flex	Each Hour	Qty 1	Estimated	<u> </u>		Actual		

Inspected

Measure 9 PressureRelief Piping Needed			Componen	ts	Inspecte			
			Estimated	1	Actual			
aterial / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
ealth and Safety Pressure relief piping ems	Each	1						
abor Labor	Hour	1						
er Detail								
		Measur	e Sub Total:			Sub Total:		
easure 10 Smoke Detector is Needed			Componen				Inspected	
nment		Otv	Estimated	<u> </u>	Ofv	Actual		
	Units	Qty 1	•		Qty		Inspected Total	
nment aterial / Labor Description / Comment ealth and Safety Smoke / Carbon detector	Units		Estimated	<u> </u>	Qty	Actual		
nment aterial / Labor Description / Comment ealth and Safety Smoke / Carbon detector ems	<i>Units</i> r Each	1	Estimated	<u> </u>	Qty	Actual		
mment aterial / Labor Description / Comment ealth and Safety Smoke / Carbon detector ems abor Labor	<i>Units</i> r Each	1	Estimated	<u> </u>	Qty	Actual		
mment aterial / Labor Description / Comment ealth and Safety Smoke / Carbon detector ems abor Labor	<i>Units</i> r Each	1 1	Estimated	<u> </u>		Actual		

	por Barrier Needed asement/Crawlspace)			Components			Inspected		
Comment									
				Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Basement / crawlspace vapor barrier	Each	1						
2 Labor	Labor	Hour	1						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Field Notes:									
		Work Or	der Gra	nd Total:		Gran	d Total:		